



Plant 2 Habitat Restoration South Shoreline



1. World War II-era Plant 2
2. Aging Plant 2 before demolition
3. Demolition of Plant 2 in 2011
4. Demolition of building overhang
5. Shoreline excavation
6. Placement of erosion control fabric and woody debris
7. Installation of native plant mats
8. Planting trees and shrubs
9. Completed restoration of south shoreline